

U.S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-440/85024(DRSS)

Docket No. 50-440

License No. CPPR-148

Licensee: Cleveland Electric Illuminating Company  
Post Office Box 5000  
Cleveland, Ohio 44101

Facility Name: Perry Nuclear Power Plant, Unit 1

Inspection At: Plant Site

Inspection Conducted: May 13-17, 1985

Date of Last Physical Security Inspection: February 20-22, 1985

Type of Inspection: Announced, Preoperational Physical Security

Inspectors: J. R. Kniceley  
J. R. Kniceley  
Physical Security Inspector

6/12/85  
Date

J. R. Kniceley for  
T. J. Madeda  
Physical Security Inspector

6/12/85  
Date

Approved By: J. R. Creed for  
J. R. Creed, Chief  
Safeguards Section

6/12/85  
Date

Inspection Summary

Inspection Conducted on May 13-17, 1985 (Report No. 50-440/85024(DRSS))

Areas Inspected: Included a review of the status of implementation; installation; operability of the security program and the preoperational testing program for security-related equipment. Specifically, the inspection covered: Security Plan and Implementing Procedures; Management Effectiveness; Security Organization; Security Program Audit; Records and Reports; Testing and Maintenance; Locks, Keys, and Combinations; Physical Barriers - Protected Areas; Physical Barriers - Vital Areas; Security System Power Supply; Lighting; Compensatory Measures; Assessment Aids; Access Control - Personnel;

850702017B 350618  
PDR ADOCK 05000440  
Q PDR

Enclosure contains  
SAFEGUARDS INFORMATION  
Upon separation this  
page is Decontrolled

Access Control - Package; Access Control - Vehicles; Detection Aids - Protected Areas; Detection Aids - Vital Areas; Alarm Stations; Communications; Personnel Training and Qualifications - General Requirements; Safeguards Contingency Plan Implementation Review; Safeguards Information and Independent Inspection Effort. This inspection involved 68 inspection-hours by two NRC inspectors.

Results: Based on the preoperational inspection, the inspectors determined the status of the security program and identified areas that must be completed prior to licensing. No items of noncompliance were identified.

Enclosure contains  
SAFEGUARDS INFORMATION  
Upon separation this  
page is Decontrolled