

Detroit
Edison

William S. Orter
Executive Vice President
Nuclear Generation

Fermi 2
6100 North Dixie Highway
Newport, Michigan 48166
(313) 586-5201



Nuclear
Operations

February 2, 1993
NRC-92-0003

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

References: 1) Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43
2) Title 10, Code of Federal Regulations,
Part 50.55(a)

Subject: Summary Report of the 1992 Inservice Inspection

Enclosed is the Summary Report of the 1992 Inservice Inspection (ISI) activities performed at Detroit Edison Company's Fermi 2 Nuclear Power Plant. This report represents a summary of the ISI activities from commercial operation (January 23, 1988) through the third refueling outage.

This report is being submitted in accordance with ASME Section XI, 1980 Edition through Winter 1981 Addenda, paragraph IWA-6230.

If there are any questions, please contact Mr. Bruce Sheffel, General Supervisor ISI/PEP, at (313) 586-1848.

Sincerely,

Enclosure

cc: w/o enclosure

ANII - M. Wilson
T. G. Colburn
Chief Inspector, Michigan Dept. of Labor, Bureau of Construction
Codes/Boiler Division - R. Aben
A. B. Davis
W. J. Kropp
M. P. Phillips
Region III

080037

9302100168 930202
PDR ADOCK 05000341
G PDR

CRIT# P162 863 681

A047