Leo Dubinski, Asst. Director for Materials, Division of Compliance Headquarters Roy C. Hageman, Director Region III, Division of Compliance 1962 Pp 1962

AM HICAN FOTASH AND CHEMICAL CORPORATION, LINDSAY CHEMICAL DIVISION, WEST CHICAGO, ILLIN IS - LICENCE NO. R-234 - EXPOSTED

C:III:JOD

The licensee was visited on June 1h, 1962 with regard to subject exposures. An inspection report of subject licensee is under preparation and appropriate citation for these overexposures will be recommended.

The licensee has notified the concerned individuals of the exposures received.

The licensee film badge reports indicate four quarterly totals in excess of 1 1/h rem of exposure. Two of these four totals (amounting to 11:00 mrem and 1380 mrem) include the exposures shown on badges reported by the supplier to be contaminated. Due to the contaminated badges, these totals do not represent the actual exposure received by individuals to whom the badges were assigned.

Two of the quarterly totals indicating overexposure appear valid. Dr. R. M. Healy, the licensee Radiation Safety Officer, stated that his investigation disclosed that the overexposures resulted from the storage in a working area of an excess number of druns containing thorium mitrate and of excess time spent by an operator for a filtering operation.

In order to prevent any recurrence of these exposures, the number of drums containing thorium mitrate which may be stored within the working area has been reduced from several dosen to six. Operators for the filtering operation are being rotated. In addition, the licensee is studying the feasibility of providing lead shielding at the filtering operation site. Also, Dr. Healy now is furnishing the foresan of each plant area a list of names of his operators who show more than hi? mrem of exposure during the first month of the quarter and 700 areas total for the first two matters of the quarter. On this list, also, is shown the exposure allessed for the remainder of the quarter so that the foresan any appropriately assign their operators.



OFFICE DAVIS DAVIS Hageman RAPKINB5-30 PDR

Form AEC-818 (Rev. 9-63)

U. S. SOVERNMENT PRINTING OFFICE 18-62761-



It is the opinion of this office that the licenses corrective measures are appropriate. This office plans no additional action in this matter other than recommendation for citation in the inspection report currently being prepared.

OFFICE >	

Form AEC-818 (Bev. 9-53)

U. S. SOVERNMENT PRINTING OFFICE 16-62761-8