Docket No. 50-454 Docket No. 50-455

Commonwealth Edison Company ATTN: Mr. Cordell Reed Vice President Post Office Box 767 Chicago, IL 60690

Gentlemen:

This refers to the routine safety inspection conducted by Dr. M. J. Oestmann of this office on June 24-28, 1985, of activities at Byron Station, Units 1 and 2 authorized by NRC Operating License No. NPF-37 and Construction Permit No. CPPR-131 and to the discussion of our findings with R. Pleniewicz and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No items of noncompliance with NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC's Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

W. D. Shafer, Chief

Emergency Preparedness and

Radiological Protection Branch

Enclosure: Inspection Reports No. 50-454/85028(DRSS); No. 50-455/85022(DRSS)

See Attached List For Distribution

8508020148 8507 PDR ADOCK 0500

## Distribution

cc w/enclosure:

- D. L. Farrar, Director of Nuclear Licensing
- V. I. Schlosser, Project Manager Gunner Sorensen, Site Project Superintendent
- R. E. Querio, Plant Manager DMB/Document Control Desk (RIDS) Resident Inspector, RIII Byron Resident Inspector, RIII Braidwood
- Phyllis Dunton, Attorney General's Office, Environmental Control Division
- D. W. Cassel, Jr., Esq. Diane Chavez, DAARE/SAFE
- W. Paton, ELD
- L. Olshan, NRR LPM
- H. S. Taylor, Quality Assurance Division
- E. Chan, ELD
- J. Stevens, NRR
- D. Weiss, Licensing Fee Management Branch

RIII Mongae Oestmann/ld/ 07/09/85 RIIIW yu Schumacher RIII Forney

