

DMB

September 26, 1985

Docket No. 50-455

Commonwealth Edison Company
ATTN: Mr. Cordell Reed
Vice President
Post Office Box 767
Chicago, IL 60690

Gentlemen:


This refers to the routine safety inspection conducted by Messrs. J. M. Hinds, Jr. and K. A. Connaughton of this office on July 16 - September 16, 1985, of activities at Byron Station Unit 2, authorized by NRC Construction Permit No. CPPR-131 and to the discussion of our findings with Mr. V. I. Schlosser and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel. No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790(a), a copy of this letter and the enclosure will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

for 
R. F. Warnick, Chief
Reactor Project Branch 1

Enclosure:

- 1. Inspection Report
No. 50-454/85025(DRP)

cc w/encl: See Distribution

8510010409 850926
PDR ADOCK 05000455
Q PDR


RIII


RIII

RIII


RIII

RIII

for 
Hinds/mm
9/19/85

for 
Lerch

for 
Forney

for 
Warnick

(YES)

Weil
9/26/85

FE01
1/1

Distribution:

D. L. Farrar, Director
of Nuclear Licensing
V. I. Schlosser, Project Manager
Gunner Sorensen, Byron Project
Construction Manager
R. E. Querio, Station
Manager
DMB/Document Control Desk (RIDS)
Resident Inspector, RIII Byron
Resident Inspector, RIII
Braidwood
Phyllis Dunton, Attorney
General's Office, Environmental
Control Division
D. W. Cassel, Jr., Esq.
Diane Chavez, DAARE/SAFE
W. Paton, ELD
L. Olshan, NRR LPM