

U-600186
L14-85(07-03)-L
1A.120

ILLINOIS POWER COMPANY



CLINTON POWER STATION, P.O. BOX 678, CLINTON, ILLINOIS 61727

Docket No. 50-461

July 3, 1985

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Subject: Potential 10CFR50.55(e) Deficiency 55-84-23
Ruskin Interlocking Blade Fire Dampers


Dear Mr. Keppler:

In Illinois Power Company letter dated April 4, 1985, (Ref: letter D. P. Hall to J. G. Keppler, U-10265), your office was provided an interim report addressing the status of the subject 10CFR50.55(e) investigation. It was anticipated at that time that a final report would be provided in approximately ninety days (90).

Sargent & Lundy is currently performing a more detailed review of the results and recommended corrective action for the subject fire dampers. It is anticipated that approximately thirty (30) additional days will be necessary to complete this review, determine reportability and provide a final report on the issue.

If you have any questions or comments regarding the status of actions taken on this issue, please contact Illinois Power Company.

Sincerely yours,


D. P. Hall
Vice President

RLC/deg

cc: NRC Resident Office
Director - Office of I&E, USNRC, Washington, DC 20555
Illinois Department of Nuclear Safety
INPO Records Center

8507190051 850703
PDR ADDCK 05000461
S PDR

JUL 5 1985

IE27 1/0