

SSER

Task: Allegation A-109

Reference No.: 4-84-A-06-4

Characterization: It is alleged that EBASCO Quality Assurance (QA) personnel stopped records reviewers when "wholesale" irregularities, some of which involved civil and perhaps criminal violations, were found in 70 of 1200 concrete placement packages which were reviewed.

Assessment of Allegation: In an EBASCO interoffice memorandum of June 6, 1983, it was stated that the "QAIRG-BOP" (quality assurance installation review group - balance of plant) was in the process of reviewing the civil QA concrete documentation in the QA vault when they were given oral instructions to cancel the review because EBASCO management claimed the documentation already had been reviewed by qualified reviewers under a qualified QA program. The June 6, 1983, EBASCO memorandum has as an attachment an EBASCO interoffice memorandum of December 9, 1982, which included discussion of a review of concrete placement packages during which each package was found not to provide adequate documentation.

On June 9, 1983, another EBASCO interoffice memorandum forwarded the two memorandums above, plus additional items, to the EBASCO Site QA Manager with a recommendation that the scope of the review of J. A. Jones documents be enlarged. On July 7, 1983, a meeting was held to discuss the review of concrete placement packages and to clarify the concerns expressed in the earlier memos which resulted in the recommendations.

On July 11, 1983, LP&L's project management group directed EBASCO to perform a 10 percent review of concrete placement packages, which began in August 1983. EBASCO (in a letter dated September 21, 1983) documented numerous deficiencies, which resulted in the initiation of a 100 percent review program of concrete placement packages. This effort, completed on January 30, 1984, addressed the placement packages for the common foundation basemat, reactor auxiliary building, reactor containment building; fuel handling building, and the shield ring and dome, under EBASCO Procedure QAI-9, Revision 1.

A review of 20 of 28 basemat placement packages by the NRC staff revealed some minor record deficiencies that were not discovered by the EBASCO review. The following three deficiencies were found.

Block-10B: Grouting documentation for core holes drilled in accordance with nonconformance report (NCR) W3-39 were not located in the placement package. EBASCO had to obtain copies of the documentation from J. A. Jones' home office during the course of the NRC Task Group effort.

Block-16: Sheet 5 of 5 of the Concrete Test Record is missing from package.

Block-5B: No cylinders were taken at the 150 cubic yards \pm 10 cubic yards Intervat (Batch Ticket No. 2734).

The concrete placement packages were sampled and reviewed by the NRC Construction Appraisal Team (CAT) prior to this current NRC staff review, but after the EBASCO review. Similar deficiencies in other concrete placement packages were found.

In the first discrepancy, the records were located. In the second case, the records were not found but, the NRC staff has no reason to suspect that the tests were not properly run or evaluated. For the third discrepancy, it was found that the exact sequence of sampling was not utilized, but the total number of test cylinders exceeded by one set (four cylinders), the number of tests required for the total concrete volume placed. This more random sampling rather than sampling on an exact schedule is considered by some to be a better method for quality control. The NRC staff does not consider this item significant.

Based on the types of discrepancies and on the small number of record discrepancies found, the NRC staff concludes that this allegation is not a significant safety issue.

Potential Violations: The failure of the licensee to have sheet 5 of the concrete test records for placement package 499-S03-16 constitutes a failure to meet Criterion XVII of Appendix B to 10 CFR 50. The regulations require that sufficient records be maintained to furnish evidence of activities affecting quality and that the records be retrievable.

Actions Required: None.

References:

1. EBASCO's "Documentation Review Instructions," QAI-9 (Revision 1).
2. EBASCO Interoffice Correspondence, Davis to Burgan, dated December 9, 1982.
3. EBASCO Interoffice Correspondence, Hill to Czyrko, dated June 6, 1983.
4. EBASCO Interoffice Correspondence, Czyrko to Stinson, dated June 9, 1983.
5. LP&L Interoffice Correspondence, Gerrets to File on July 7, 1983, Meeting, dated July 11, 1983.
6. EBASCO Interoffice Correspondence, Cutrona to Milhiser, dated September 21, 1983.
7. LP&L Interoffice Correspondence, Davis to Gerrets, dated December 22, 1983.

8. Concrete Placement Packages for Blocks 1, 2, 4, 5A, 5B, 6, 7A, 7B, 8A, 8B, 9A, 9B, 10A, 10B, 11A, 11B, 14A, 15, 16, and 17.

Statement Prepared By: John K. Devers _____ Date _____

Statement Prepared By: NiTesh C. Chokshi _____ Date _____

Statement Prepared By: Robert E. Shewmaker _____ Date _____

Reviewed By: Team Leader _____ Date _____

Reviewed By: Site Team Leader(s) _____ Date _____

Approved By: Task Management _____ Date _____

SSER

Task: Allegation A-109

Reference No.: 4-84-A-06-4

Characterization: It is alleged that EBASCO Quality Assurance (QA) personnel stopped records reviewers when "wholesale" irregularities, some of which involved civil and perhaps criminal violations, were found in 70 of 1200 concrete placement packages which were reviewed.

Assessment of Allegation: In an EBASCO interoffice memorandum of June 6, 1983, it was stated that the "QAIRG-BOP" (quality assurance installation review group - balance of plant) was in the process of reviewing the civil QA concrete documentation in the QA vault when they were given oral instructions to cancel the review because EBASCO management claimed the documentation already had been reviewed by qualified reviewers under a qualified QA program. The June 6, 1983 EBASCO memorandum has as an attachment an EBASCO interoffice memorandum of December 9, 1982, which included discussion of a review of concrete placement packages during which each package was found not to provide adequate documentation.

On June 9, 1983, another EBASCO interoffice memorandum forwarded the two memorandums above, plus additional items, to the EBASCO Site QA Manager with a recommendation that the scope of the review of J. A. Jones documents be enlarged. On July 7, 1983, a meeting was held to discuss the review of concrete placement packages and to clarify the concerns expressed in the earlier memos which resulted in the recommendations.

On July 11, 1983, LP&L's project management group directed EBASCO to perform a 10% review of concrete placement packages, which began in August 1983. EBASCO (in a letter dated September 21, 1983) documented numerous deficiencies, which resulted in the initiation of a 100% review program of concrete placement packages. This effort, completed on January 30, 1984, addressed the placement

packages for the common foundation basemat, reactor auxiliary building, reactor containment building; fuel handling building, and the shield ring and dome, under EBASCO Procedure QAI-9, Revision 1.

A review of 20 of 28 basemat placement packages by the NRC staff revealed some minor record deficiencies that were not discovered by the EBASCO review. The following three deficiencies were found.

Block-10B: Grouting documentation for core holes drilled in accordance with nonconformance report (NCR) W3-39 were not located in the placement package. EBASCO had to obtain copies of the documentation from J. A. Jones' home office during the course of the NRC Task Group effort.

Block-16: Sheet 5 of 5 of the Concrete Test Record is missing from package.

Block-5B: No cylinders were taken at the 150 cubic yards \pm 10 cubic yards interval (Batch Ticket No. 2734).

The concrete placement packages were sampled and reviewed by the NRC Construction Appraisal Team (CAT) prior to this current NRC staff review, but after the EBASCO review. Similar deficiencies in other concrete placement packages were found.

In the first discrepancy, the records were located. In the second case the records were not found, but the NRC staff has no reason to suspect that the tests were not properly run or evaluated. For the third discrepancy, it was found that the exact sequence of sampling was not utilized, but the total number of test cylinders exceeded by one set (four cylinders), the number of tests required for the total concrete volume placed. This more random sampling rather than sampling on an exact schedule is considered by some to be a better method for quality control. The NRC staff does not consider this item significant.

Based on the types of discrepancies and on the small number of record discrepancies found, the NRC staff concludes that this allegation is not a significant safety issue.

Potential Violations: The failure of the licensee to have sheet 5 of the concrete test records for placement package 499-S03-16 constitutes a failure to meet Criterion XVII of Appendix B to 10 CFR 50. The regulations require that sufficient records be maintained to furnish evidence of activities affecting quality and that the records be retrievable.

Actions Required: None.

References

1. EBASCO's "Documentation Review Instructions," QAI-9 (Revision 1)
2. EBASCO Interoffice Correspondence, Davis to Burgan, dated December 9, 1982.
3. EBASCO Interoffice Correspondence, Hill to Czyrko, dated June 6, 1983.
4. Ebasco Interoffice Correspondence, Czyrko to Stinson, dated June 9, 1983.
5. LP&L Interoffice Correspondence, Gerrets to File on July 7, 1983 Meeting, dated July 11, 1983.
6. EBASCO Interoffice Correspondence, Cutrona to Milhisier, dated September 21, 1983.
7. LP&L Interoffice Correspondence, David to Gerrets, dated December 22, 1983.
8. Concrete Placement Packages for Blocks 1, 2, 4, 5A, 5B, 6, 7A, 7B, 8A, 8B, 9A, 9B, 10A, 10B, 11A, 11B, 14A, 15, 16, and 17.

- 4 -

Statement Prepared By: _____ Date
John K. Devers

Statement Prepared By: _____ Date
Nilesh C. Chokshi

Statement Prepared By: _____ Date
Robert E. Shewmaker

Reviewed By: _____ Date
Team Leader

Reviewed By: _____ Date
Site Team Leader(s)

Approved By: _____ Date
Task Management

SSER

Task: Allegation A-109

Reference No.: 4-84-A-06-4

Characterization: It is alleged that EBASCO Quality Assurance (QA) personnel stopped records reviewers when "wholesale" irregularities, some of which involved civil and perhaps criminal violations, were found in 70 of 1200 concrete placement packages which were reviewed.

Assessment of Allegation: In an EBASCO interoffice memorandum of June 6, 1983, it was stated that the "QAIRG-BOP" (quality assurance installation review group - balance of plant) was in the process of reviewing the civil QA concrete documentation in the QA vault when they were given oral instructions to cancel the review because EBASCO management claimed the documentation already had been reviewed by qualified reviewers under a qualified QA program. The June 6, 1983 EBASCO memorandum has as an attachment an EBASCO interoffice memorandum of December 9, 1982, which included discussion of a review of concrete placement packages during which each package was found not to provide adequate documentation.

On June 9, 1983, another EBASCO interoffice memorandum forwarded the two memorandums above, plus additional items, to the EBASCO Site QA Manager with a recommendation that the scope of the review of J. A. Jones documents be enlarged. On July 7, 1983, a meeting was held to discuss the review of concrete placement packages and to clarify the concerns expressed in the earlier memos which resulted in the recommendations.

On July 11, 1983, LP&L's project management group directed EBASCO to perform a 10% review of concrete placement packages, which began in August 1983. EBASCO (in a letter dated September 21, 1983) documented numerous deficiencies, which resulted in the initiation of a 100% review program of concrete placement packages. This effort, completed on January 30, 1984, addressed the placement

packages for the common foundation basemat, reactor auxiliary building, reactor containment building; fuel handling building, and the shield ring and dome, under EBASCO Procedure QAI-9, Revision 1.

A review of 20 of 28 basemat placement packages by the NRC staff revealed some minor record deficiencies that were not discovered by the EBASCO review. The following three deficiencies were found.

Block-10B: Grouting documentation for core holes drilled in accordance with nonconformance report (NCR) W3-39 were not located in the placement package. EBASCO had to obtain copies of the documentation from J. A. Jones' home office during the course of the NRC Task Group effort.

Block-16: Sheet 5 of 5 of the Concrete Test Record is missing from package.

Block-5B: No cylinders were taken at the 150 cubic yards \pm 10 cubic yards interval (Batch Ticket No. 2734).

The concrete placement packages were sampled and reviewed by the NRC Construction Appraisal Team (CAT) prior to this current NRC staff review, but after the EBASCO review. Similar deficiencies in other concrete placement packages were found.

In the first discrepancy, the records were located. In the second case the records were not found, but the NRC staff has no reason to suspect that the tests were not properly run or evaluated. For the third discrepancy, it was found that the exact sequence of sampling was not utilized, but the total number of test cylinders exceeded by one set (four cylinders), the number of tests required for the total concrete volume placed. This more random sampling rather than sampling on an exact schedule is considered by some to be a better method for quality control. The NRC staff does not consider this item significant.

Based on the types of discrepancies and on the small number of record discrepancies found, the NRC staff concludes that this allegation is not a significant safety issue.

Potential Violations: The failure of the licensee to have sheet 5 of the concrete test records for placement package 499-S03-16 constitutes a failure to meet Criterion XVII of Appendix B to 10 CFR 50. The regulations require that sufficient records be maintained to furnish evidence of activities affecting quality and that the records be retrievable.

Actions Required: None.

References

1. EBASCO's "Documentation Review Instructions," QAI-9 (Revision 1)
2. EBASCO Interoffice Correspondence, Davis to Burgan, dated December 9, 1982.
3. EBASCO Interoffice Correspondence, Hill to Czyrko, dated June 6, 1983.
4. Ebasco Interoffice Correspondence, Czyrko to Stinson, dated June 9, 1983.
5. LP&L Interoffice Correspondence, Gerrets to File on July 7, 1983 Meeting, dated July 11, 1983.
6. EBASCO Interoffice Correspondence, Cutrona to Milhiser, dated September 21, 1983.
7. LP&L Interoffice Correspondence, David to Gerrets, dated December 22, 1983.
8. Concrete Placement Packages for Blocks 1, 2, 4, 5A, 5B, 6, 7A, 7B, 8A, 8B, 9A, 9B, 10A, 10B, 11A, 11B, 14A, 15, 16, and 17.

Statement Prepared By: _____

John K. Devers

Date

Statement Prepared By: _____

Nilesh C. Chokshi

Date

Statement Prepared By: _____

Robert E. Shewmaker

Date

Reviewed By: _____

Team Leader

Date

Reviewed By: _____

Site Team Leader(s)

Date

Approved By: _____

Task Management

Date

Document Name:
SSER A-109

Requestor's ID:
CONNIE

Author's Name:

Document Comments: