




Public Service

Public Service
Company of Colorado

16805 WCR 19 1/2, Platteville, Colorado 80651

July 18, 1985
Fort St. Vrain
Unit No. 1
P-85252

Regional Administrator
Region IV
U. S. Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 1000
Arlington, TX 76011



Attention: Mr. E. H. Johnson

Docket No. 50-267

SUBJECT: Provisions to Preclude Manual
Inward Overtravel of Control Rods

REFERENCE: NRC Letter, Johnson to Lee,
Dated July 12, 1985 (G-85270)

Dear Mr. Johnson:

In Attachment 3 to the referenced letter, the Nuclear Regulatory Commission (NRC) states that Public Service Company of Colorado (PSC) ". . . should confirm that all procedures in which rod travel beyond the full-in limit could occur contain appropriate cautions and controls to reduce the likelihood of damage to potentiometers and their couplings." This letter serves as notice to the NRC that PSC is currently including such procedural controls (if not already present) in all appropriate System Operating Procedures, Surveillance Requirement Procedures, and Emergency Procedures. This task will be completed by July 19, 1985.

If you have any questions, please contact Mr. M. H. Holmes at (303) 571-8409.

Sincerely,

J. W. Gahm
Manager, Nuclear Production
Fort St. Vrain Nuclear
Generating Station

JWG:FJN/skd

85-653

8508020556 850718
PDR ADOCK 05000267
P PDR

7/20/85
Return original
to RIV
1/0