



RECEIVED
NRC

Arizona Nuclear Power Project

P.O. BOX 52034 • PHOENIX, ARIZONA 85072-2034

1985 JUL 17 AM 11:14

July 15, 1985
ANPP-33012-TDS/TPS

REGION V IBE

52-528
50-539
50-537

U. S. Nuclear Regulatory Commission
Region V
1450 Maria Lane - Suite 210
Walnut Creek, California 94596-5368

Attention: Mr. D. F. Kirsch, Acting Director
Division of Reactor Safety and Projects

Subject: Time Extension for Report - DER 85-16
A 50.55(e) Potentially Reportable Deficiency Relating to
AHU Fan Wheel Hub Casting Failure
File: 85-019-026; D.4.33.2

Reference: (A) Telephone conversation between R. C. Sorensen and
P. J. Coffin on May 7, 1985
(B) ANPP-32787, dated June 6, 1985 (Interim Report)

Dear Sir:

The NRC was notified of a potentially reportable deficiency in
Reference (A), and an Interim Report was transmitted by Reference (B).
At that time, it was estimated that a Final Report would be available
by July 12, 1985.

Due to the extensive investigation and evaluation required, it is now
expected that this information will be finalized by August 14, 1985,
at which time a complete report will be submitted.

There is no new information or change to the Interim Report at this
time.

Very truly yours,

E. E. Van Brunt, Jr.
Executive Vice President
Project Director

EEVB/TPS/jb

cc: See Page Two

8508050118 850715
PDR ADOCK 05000528
S PDR

10
IE-27
27

Mr. D. F. Kirsch
DER 85-16
Page Two

cc: Richard DeYoung, Director
Office of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

D. B. Karner
W. E. Ide
D. B. Fasnacht
A. C. Rogers
L. A. Souza
D. E. Fowler
T. D. Shriver
C. N. Russo
B. S. Kaplan
J. R. Bynum
J. M. Allen
D. Canady
A. C. Gehr
W. J. Stubblefield
W. G. Bingham
R. L. Patterson
R. W. Welcher
H. D. Foster
D. R. Hawkinson
R. P. Zimmerman
M. L. Clyde
B. T. Parker
T. J. Bloom
D. N. Stover
J. D. Houchen
J. E. Kirby

Records Center
Institute of Nuclear Power Operations
1100 Circle 75 Parkway, Suite 1500
Atlanta, GA 30339