

BOSTON EDISON COMPANY
800 BOYLSTON STREET
BOSTON, MASSACHUSETTS 02199

WILLIAM D. HARRINGTON
SENIOR VICE PRESIDENT
NUCLEAR

August 1, 1985

BECO 85-138

Hugh L. Thompson, Jr., Director
Division of Licensing
Office of Nuclear Reactor Regulation
U.S. Nuclear Regulatory Commission
Washington, D. C. 20555

License DPR-35
Docket 50-293

Subject: Environmental Qualification
of Electrical Equipment at
Pilgrim Nuclear Power Station

Reference: 1) NRC Safety Evaluation Report
dated March 26, 1985

Dear Sir:

The NRC issued the safety evaluation report dated March 26, 1985 addressing the environmental qualification of electrical equipment important to safety at Pilgrim Nuclear Power Station for compliance with the requirements of 10CFR50.49. The safety evaluation was based on the NRC review of BECo letters dated July 9, August 3, September 24, 1984 and January 29, 1985.

Boston Edison has reviewed the safety evaluation report (SER) issued by the NRC against BECo submittals and has identified certain errors and omissions on the SER. They are listed below for your info and record.

Safety Evaluation

<u>Report</u> <u>Page #</u>	<u>Typographical Errors</u> <u>Printed Pilgrim Tag No.</u>	<u>Should Be</u>
1	MO 1201-16	MO 1301-16
2	MO 401 A/B	MO 4010 A/B
2	MO 406 A/B	MO 4060 A/B
2	AO 201-1 A/D	AO 203-1A thru 1D
2	AO 203-2 A/D	AO 203-2A thru 2D
4	DPIS-261, 2A-2	DPIS-261-2A thru 2S
5	CX2, CX4, 540, CX8	CX2, CX4, 520, CX8
6	S1, S37, GXG, Z3	S1, S37, CXG, Z3
6	Z3A, 548, C02, C03	Z3A, 548, C02, C03

8508060046 850801
PDR ADDCK 05000293
P PDR

A048
110

Mr. Hugh L. Thompson, Director
August 1, 1985
Page 2

Omissions

Page

3

C163 should be included with group C152, 153, . . . 159

6

PS 263 - 55C, D TER 201 Barksdale Pressure Switches

We would be pleased to answer any questions you may have regarding this letter.

Very truly yours,

TAV/ns

A handwritten signature in dark ink, appearing to read "W. D. Harrington" with a stylized flourish at the end.

W. D. Harrington