

APPENDIX A
NOTICE OF VIOLATION

Gulf States Utilities
River Bend Station

Docket: 50-458
Permit: CPPR-145

During an NRC inspection conducted April 3-8, 1985, a violation of NRC requirements was identified. The violation involved an inadequate procedure. In accordance with the "General Statement of Policy and Procedure for NRC Enforcement Actions," 10 CFR Part 2, Appendix C (1985), the violation is listed below:

Inadequate Test Procedure

10 CFR Part 50, Appendix B, Criterion V states that procedures, drawings, and instructions shall be used to control activities affecting quality related activities.

Contrary to the above, Preoperational Procedure 1-PT-57-1 failed to identify six differential pressure instruments and one motor operated valve required for the valve lineup to conduct the Intergrated Leak Test.

This is a Severity Level V Violation. (Supplement II.E)(458/85-31-01)

Pursuant to the provisions of 10 CFR 2.201, Gulf States Utilities is hereby required to submit to this office, within 30 days of the date of this Notice, a written statement or explanation in reply, including: (1) the reason for the violation if admitted, (2) the corrective steps which have been taken and the results achieved, (3) the corrective steps which will be taken to avoid further violations, and (4) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending the response time.

Dated at Arlington, Texas
this 2d day of Aug., 1985

8508060273 850802
PDR ADOCK 05000458
G PDR