NRC Form 591		U.S. NUCLEAR REGULATORY COMMISSION
(12-81) 10 CFR 2.201	SAFETY INSPECTION	DESIGNATED ORIGINAL
		Certified By: M. McKamaco
Touch stone Environmente, 33 Thompson Street Winchester, MA 01890	Consultant USN Region 631 P King 2	
A 44	-20626-01	7/16/85
Licensee: The inspection was an examination of the activities conduct Regulatory Commission's (NRC) rules and regulations and the and representative records, interviews, with personnel, and of the second of this inspection, no violations were considered. 2. The inspector also verified the steps you have taken to those actions at this time.	ne conditions of your license. The inspector observations by the inspector. The finding observed. o correct the violations identified during	tion consisted of selective examinations of procedures ags as a result of this inspection are as follows: the last inspection. We have no further questions on
THIS IS A NOTICE OF VIOLATION which is require	red to be posted in accordance with 10 C	
of a		was not properly posted to indicate the presence . 10 CFR 20.203(b), (c), (d), (e) or 34.42.
B. Containers located in		of sealed sources were not performed at the proper
requestions. To CFR		· ·
D. Records of	or License Condition	Number were not properly maintained.
E. Documents were not properly posted or otherwise	e made available. 10 CFR 19.11.	
F. Reports or notifications of		were not made in accordance
with 10 CFR	or License Condition	Number
		RETURN ORIGINAL TO REGION I
Пк		1E:07.
Thereby state that within 30 days the actions described by a This statement of corrective actions is made in accordance with NRC. 8508070264 850716 20-20626-01 PDR SIGNATURE - LICENSEE		M. Lipp 1/16/85