



JOE WILLIAMS, JR.
Senior Vice President - Nuclear
(419) 249-2300
(419) 249-5223

Docket No. 50-346

License No. NPF-3

Serial No. 1190

October 10, 1985

Director of Nuclear Reactor Regulation
Attention: Mr. John F. Stolz
Operating Reactor Branch No. 4
Division of Licensing
United States Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Stolz:

Toledo Edison has been reviewing the adequacy of the specified subcooling margin for the Davis-Besse Nuclear Power Station Unit No. 1 as stated in our letter dated July 15, 1985 (Serial No. 1169). We have determined that a revision to our specified subcooling margin is appropriate.

Due to the June 9, 1985 event, our resources are heavily allocated to the completion of related investigations and the implementation of corrective actions. However, we plan to revise and approve the appropriate procedures concerning subcooling margin and provide your office with any necessary submittals, prior to Restart.

Very truly yours,

A handwritten signature in cursive script, appearing to read 'J. Williams, Jr.' followed by the initials 'JKB'.

JW:GAB:lah

cc: DB-1 NRC Resident Inspector

8510160065 851010
PDR ADOCK 05000346
P PDR

*Acc
1/0*