

UNIT SHUTDOWNS AND POWER REDUCTIONS

DOCKET NO. 50 - 352

UNIT NAME LIMERICK UNIT 1

DATE MAY 15, 1985

REPORT MONTH APRIL, 1985

COMPLETED BY PHILADELPHIA ELECTRIC COMPANY

W.M. ALDEN
ENGINEER-IN-CHARGE
NUCLEAR SECTION
GENERATION DIVISION-NUCLEAR
TELEPHONE (215) 841-5022

NO.	DATE	TYPE (1)	DURATION (HOURS) (2)	REASON (3)	METHOD OF SHUTTING DOWN REACTOR (4)	LICENSEE EVENT REPORT # (5)	SYSTEM CODE (6)	COMPONENT CODE (7)	CAUSE AND CORRECTIVE ACTION TO PREVENT RECURRENCE
1	850413	F	48.3	B	4	N/A	TA	TURBIN	TURBINE VIBRATIONS WERE INVESTIGATED.

(1)

(2)

(3)

(4)

(5)

- FORCED
- SCHEDULED

REASON

A - EQUIPMENT FAILURE (EXPLAIN)
B - MAINTENANCE OR TEST
C - REFUELING
D - REGULATORY RESTRICTION
E - OPERATOR TRAINING + LICENSE EXAMINATION
F - ADMINISTRATIVE
G - OPERATIONAL ERROR (EXPLAIN)
H - OTHER (EXPLAIN)

METHOD

1 - MANUAL
2 - MANUAL SCRAM
3 - AUTOMATIC SCRAM
4 - OTHER (EXPLAIN)

EXHIBIT G - INSTRUCTIONS
FOR PREPARATION OF DATA
ENTRY SHEETS FOR LICENSEE
EVENT REPORT (LER)
FILE (NUREG-0161)

EXHIBIT I - SAME SOURCE

8508090578 850703
PDR ADOCK 05000352
R PDR