



Carolina Power & Light Company

Brunswick Steam Electric Plant
P. O. Box 10429
Southport, NC 28461-0429
August 2, 1985

FILE: B09-13510C
SERIAL: BSEP/85-1392

Dr. J. Nelson Grace, Administrator
U.S. Nuclear Regulatory Commission
Suite 2900
101 Marietta Street NW
Atlanta, GA 30323

85 AUG 5 48:56

BRUNSWICK STEAM ELECTRIC PLANT UNIT 1
DOCKET NO. 50-325
LICENSE NO. DPR-71
SUPPLEMENT TO SPECIAL REPORT PER TECHNICAL SPECIFICATION 3.7.8a
AND PURSUANT TO TECHNICAL SPECIFICATION 6.9.2 (1-SR-85-6)

Dear Dr. Grace:

In the original submittal of 1-SR-85-6, sent to your office on July 25, 1985 (Serial: BSEP/85-1346), it was incorrectly reported that a fire barrier penetration seal, identified as CB-2-224-21, was removed during plant modification work. The correct identification of the reported subject penetration seal is CB-2-244-21.

Very truly yours,

C. R. Dietz, General Manager
Brunswick Steam Electric Plant

RMP/jo

Enclosure

cc: NRC Document Control Desk

8508120068 850802
PDR ADOCK 05000325
S PDR

110
IE19