

DMB

Docket No. 50-346

License No. NPF-3

Serial No. 1-556

July 26, 1985



PRIORITY ROUTING

First	Second
WA	RC
WPA	RTG
WPP	SGA
WPS	JML
WRSS	DL
DRMA	DI
	PRO

orig

FILE *has*

Mr. James G. Keppler
 Regional Administrator
 United States Nuclear Regulatory Commission
 Region III
 799 Roosevelt Road
 Glen Ellyn, IL 60137

Dear Mr. Keppler:

Enclosed is Revision 3 of the Safety-Related Piping System Support and Hanger Discrepancies Summary Report for the Davis-Besse Nuclear Power Station Unit No. 1. As requested by your Staff, Toledo Edison is updating this report weekly and submitting it to your office to keep your Staff notified in writing of any new discrepancies identified on safety-related piping system hangers or supports. This report also provides the status of discrepancies with regards to their disposition.

Very truly yours,

Joe Williams, Jr.
 Joe Williams, Jr.
 Senior Vice President, Nuclear

JW:DRW:lah
enclosure

cc: DB-1 NRC Resident Inspector
 D. Danielson, NRC Region III
 I. N. Jackiw, NRC Region III

JUL 29 1985

8508130087 850726
 PDR ADDOCK 05000346
 R PDR

1/1
IE01