

PECU Energy Company Limerick Generating Station PO Box 2300 Sanatoga, PA 19464-0920 610 718 2000

10CFR50.73

January 15, 1997

Docket No. 50-353

License No. NPF-85

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

SUBJECT: Licensee Event Report

Limerick Generating Station - Unit 2

This LER reports a non-compliance with a specific provision of the Fire Protection Program for Unit 2. The electrical power to two motor operated valves was not removed during start-up following a planned maintenance outage. These valves are required to be closed and de-energized to protect a high/low pressure system interfaces in the event of a fire in certain areas of the plant. This resulted in a failure to meet a License Condition for Unit 2.

Reference: Report Number: Revision Number: Event Date: Discovery Date:

Report Date: Facility:

Docket No. 50-353 2-96-008

00

December 14, 1996 December 16, 1996 January 15, 1997

Limerick Generating Station

P.O. Box 2300, Sanatoga, PA 19464-2300

2300

This LER is being submitted pursuant to the requirements of License Condition 2.E for Unit 2.

Rolent Source

cc: H. J. Miller, Administrator Region I, USNRC

N. S. Perry, USNRC Senior Resident Inspector, LGS

1/1 IE22

DBN:dbn