

JUL 19 1985

Docket Nos. 50-272  
50-311

Public Service Electric and Gas Company  
ATTN: Mr. Richard A. Uderitz  
Vice President - Nuclear  
P. O. Box 236  
Hancock's Bridge, New Jersey 08038

Gentlemen:

Subject: Inspection Nos. 50-272/84-46 and 50-311/84-46

This refers to your letter dated May 28, 1985, in response to our letter dated April 2, 1985.

Thank you for informing us of the corrective and preventive actions documented in your letter. These actions will be examined during a future inspection of your licensed program.

Your cooperation with us is appreciated.

Sincerely,

Original Signed By:  
Jacque P. Durr

Stewart D. Ebnetter, Director  
Division of Reactor Safety

cc:

R. L. Mittl, General Manager - Nuclear Assurance and Regulation  
J. M. Zupko, Jr., General Manager - Salem Operations  
E. A. Liden, Manager - Nuclear Licensing and Regulation  
C. P. Johnson, Manager - Quality Assurance Nuclear Operations  
P. M. Krishna, Manager - Nuclear Review Board  
A. J. Pietrofitta, General Manager, Power Production Engineering, Atlantic Electric  
M. J. Wetterhahn, Esquire  
R. Fryling, Jr., Esquire  
Public Document Room (PDR)  
Local Public Document Room (LPDR)  
Nuclear Safety Information Center (NSIC)  
NRC Resident Inspector  
State of New Jersey

bcc:

Region I Docket Room (with concurrences)  
DRP Section Chief

8508190401 850719  
PDR ADOCK 05000272  
G PDR

JE02

RI:DRS  
Krasopoulos  
6/18/85

RI:DRS  
Anderson  
6/24/85

RI:DRS  
Durr  
7/17/85

Public Service  
Electric and Gas  
Company

Corbin A. McNeill, Jr.  
Vice President  
Nuclear

Public Service Electric and Gas Company, P.O. Box 236, Hatcocks Bridge, NJ 08038 609-339-4800

May 28, 1985

Dr. Thomas E. Murley, Regional Administrator  
Region 1  
U.S. Nuclear Regulatory Commission  
631 Park Avenue  
King of Prussia, PA 19406

Dear Dr. Murley:

UNRESOLVED ITEMS - COMBINED INSPECTION  
REPORT NOS. 50-272/84-46 AND 50-311/84-46  
SALEM GENERATING STATION  
UNIT NOS. 1 AND 2  
DOCKET NOS. 50-272 AND 50-311

Your letter dated April 2, 1985 on the subject inspection identified two unresolved items, namely:

- 1). Inadequate fire drill participation by fire brigade members, and
- 2). Incomplete Biennial audit of the facility fire protection program.

Information concerning these items was provided to the NRC inspector (Mr. A. Krasopoulos) during his supplemental site visit (April 1-4, 1985) and in a subsequent meeting with him in your office on April 25, 1985. It is our understanding that the first item is closed. Attachment 1 provides the information to close the second item.

Should you have any questions, please contact us.

Sincerely,



Attachment

C Mr. Donald C. Fischer  
Licensing Project Manager

Mr. Thomas J. Kenny  
Senior Resident Inspector

8506070335

ATTACHMENT 1

Unresolved Item - Additional Information.

Incomplete Biennial Audit (50-272/84-46-02 & 50-311/84-46-02)

Technical Specification 6.5.2.8.h requires that the facility fire protection program and implementing procedures be audited at least once per 24 months.

OA Programmatic controls associated with fire protection are audited as a part of the two-year audit cycle required by ANS 3.2/ ANSI N18.7. In addition, fire protection - unique administrative controls, such as fire brigade training, control of combustibles and ignition sources, and inspection/test of fire protection equipment are audited annually.

As a result of discussions with Mr. A. Krasopoulos, it is our understanding that the following additional measures will close this item:

1. Future programmatic audits of Design Control will address fire protection-unique controls.
2. Annual fire protection audits will include examination of document controls associated with fire protection procedures.

These measures will be implemented by November 30, 1985.