

Philippine

MAR 2 1981

TO ALL ARRANGEMENTS' ADMINISTRATORS(19)

Dr. Agustin Alonso, Head
Radiological Protection and Nuclear
Safety Division
Junta de Energia Nuclear
Avenida Complutense
Madrid 3, Spain

Dear Dr. Alonso:

Enclosed are reports on the Indian Point 3 Low Pressure Turbine incident, and two generic issue reports on Low Pressure (LP) Turbine Disc Cracking. The NRC is currently evaluating the LP disc cracking as a generic problem. I will send a copy of any official NRC reports on the LP Turbine Disc Cracking problem as they become available to this office.

Sincerely,

Original signed by
Joseph D. Lafleur, Jr.

Joseph D. Lafleur Jr.
Deputy Director
Office of International Programs

Enclosures:

1. Preliminary Notification PNO-I-81-16
2. Report to Commission, January 81,
Turbine Disc Cracking
3. IE Information Notice No. 79-37,
Low Pressure Turbine Disc Cracking

bcc: JDLafleur w/o encl.
HJFaulkner "
MMallory w/encl.

FILE

8509200145 850807
PDR FOIA
SCHLEMMB4-559 PDR

118

OFFICE	IP	IP	IP				
NAME	MMALLORY	HFAULKNER	JDLAFLEUR				
DATE	3/2/81	3/ /81	3/ /81				