DOD

(7-91) 10 CFR 2.201	SAFETY	INSPECTION	7/	Page 1 of
The Mount Sina Medical Conter One Mount Sina Drive Cleveland, OH 44106-4198		U S N 801 V	REGION III US NUCLEAR REGULATORY COMMISSION 801 WARRENVILLE ROAD LISLE IL 60532-4351	
3. DOCKET NUMBER(S)			5. DATE OF INSPECTION February 24, 1997	
LICENSEE. The inspection was an examination of the acti Regulatory Commission (NRC) rules and regulatory commission (NRC) rules and regulatory commission (NRC) rules and regulatory records, intervited lows: 1. Within the acope of this inspection, in the second commission of the action of the second commission (NRC) rules and regularized commission (NRC) rules and rules are rules and rules and rules are rules are rules and rules are rules are rules and rules are rules are rules are rules and rules are rules are rules are rules are rules are rules and rules are r	lations and the condition ews with personnel, and no violations were observable you have taken to corre	ns of your license. The in observations by the insp	spection consisted of selective ector. The findings as a result	examinations of of this inspection are as
A. indicate the presence of a	quired to be posted in ac	coordance with 10 CFR 19	was not properly	y posted to 8(b),(c),(d),(e) or 34.42.
D. Documents were not properly E. Reports or notification of	or License Condition	Number	were not prop	erly maintained.
10 CFR 35.5	o(b)(a): Date	(colibrator 1	insarity tests	
I hereby state that, within 30 days, the actions above. This statement of corrective actions is unless required by the NFIC.	described by me to the made in accordance with	Inspector will be taken to h the requirements of 10	correct the violations identified CFR 2.201. No further respons	d in the items checked se will be submitted
SIGNATURE - LICENSEE While & Lynnin from	DATE 2/26/97	SIGNATURE - NRC IN		DATE 2/36/97

NRC FORM 591 Pert 1 (7-91)