(12-81) 10 CFR 2.201		SAFETY I	NSPECTION	U.S. NUCLEAR REGULATORY COMMISSION	
BTR Paper Group Haryck Pormex Division P.O. Box 471 Wake Forest, North Carolina		27587		ear Regulatory Commission letta St., Suite 2900	
3. DOCKET NUMBER		4. LICENSE NUMBER(S		5. DATE OF INSPECTION	
MARXAMANI Licensee:	030-20201	32-1846	5-02	11-20-1985	-
2. The inspector als those actions at 1 3. During this inspector. THIS IS A NOTION.	of this inspection, no violation verified the steps you have this time.	e taken to correct the violat es, as checked below, were is required to be posted in	ions identified during the I in violation of NRC requir accordance with 10 CFR 1	9.11.	
of a	cated in			was not properly posted to indicate the presence 10 CFR 20.203(b), (c), (d), (e) or 34.42 were not properly	
Пс				of sealed sources were not performed at the proper	
frequencies.	10 CFR		License Con	dition Number	
D. Records of				were not properly maintained.	
10 CFR			or License Condition Numb		
	vere not properly posted or o				
	otifications of			were not made in accordance	
Пн					
	8512120315 85 REG2 LIC30 32-18485-02	1120 PDR			
К	3E-10407-VE				
Control for the control of the contr			The second secon		ei.

I hereby state that within 30 days the actions described by me to the inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.

DATE

SIGNATURE - LICENSEE

Claude a. Rome 11/20 SIGNATURE - NACINSPECTOR 01