

Region IV 611 Ryan Plaza Drive, Suite 1000 Arlington, Texas 76011

Attn: Mr. Jerry Everett Material Licensing Branch

RE: NRC License No. 49-12994-01 - Exp. 6/30/8

Dear Mr. Everett:

We have received notice of expiration of the above captioned radioactive material license. Please be advised that Goodwell, Inc. wishes to continue well logging operations under our current license, pending renewal, in accordance with license conditions and NRC regulations. We enclose our check in the amount of \$460.00 to cover the licensing fee.

We have prepared and submit herewith in duplicate a renewal application and an Operating & Emergency Procedures Manual. This application has been completed to indicate all AmBe 241 source models, not to exceed 3 Curies, although we have sources of varying activity from 50 mCi to 3 Ci. Likewise the Cesium 137 source models cover sources up to 2 Curies, and we have sources of varying activity from 2.2 mCi to 2 Ci. We wish to reference application dated 4/24/81 and letter dated 7/8/81 with accompanying Training Manual for in-house use. These items resulted in Amendment #15, and should be included in our renewal license. Applications and letters dated 9/25/78, 4/12/79 and 10/15/80 are no longer relavent to our operations, or have been incorporated into this renewal application, therefore, they can be deleted. The previously submitted Radiation Safety Procedures manual is to be replaced by the enclosed Operating & Emergency Procedures Manual.

We have been assisted in the preparation of this submittal by Keith Moon of Support Consultants. If you need additional information or clarification, please contact Tim Bickett, our RPO, or Ar. Moon, as they are authorized to represent Goodwell, Inc. in the acquisition of this license renewal. We trust the enclosed documents and above references will allow you issue the renewal license at an early Reater DEVIEWS

pm Enclosures cc: SC&A Inc. By. Brown Grig To Action Compl. 6/4/19

Date.

Gerald D. Bullard

Sincerely,

President

60296

PDR

8510240486 850821

REG4 LIC30 49-12994-01

1984