



Commonwealth Edison
One First National Plaza, Chicago, Illinois
Address Reply to: Post Office Box 767
Chicago, Illinois 60690

September 11, 1984

Mr. James G. Keppler
Regional Administrator
Region III
U. S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, IL 60137

Subject: Braidwood Station Units 1 and 2
Response to Inspection Report
Nos. 50-456/84-05 and 50-457/84-05
NRC Docket Nos. 50-456 and 50-457

References (a): R. F. Warnick Letter to Cordell Reed
dated July 2, 1984

(b): D. L. Farrar Letter to J. G. Keppler
dated August 10, 1984

Dear Mr. Keppler:

This letter provides additional response to the inspection conducted by Messrs. H. W. Kerch, R. H. Harris and R. M. Campbell of the Region I Office on March 26 through April 6, and April 9 through 20, 1984, of activities at our Braidwood Station. Reference (a) indicated that certain activities appeared to be in non-compliance with NRC requirements. The Commonwealth Edison Company response to the Notice of Violation as appended to Reference (a) was provided by reference (b).

On September 11, 1984, we discussed with Mr. R. F. Warnick of your office that the dates of full compliance on two items are now as follows:

- C.1.a. The area of incomplete fusion will be repaired and reinspected by November 1, 1984.
- C.1.b. The repair, reinspection, and additional formal instruction will be completed by November 1, 1984.


8412180530 841213
PDR ADOCK 05000456
Q PDR

SEP 12 1984

-2-

This letter only revises the dates of full compliance. The actions being performed are as stated in Reference (b).

Very truly yours,

A handwritten signature in cursive script, appearing to read "David H. Smith". The signature is written in dark ink and is positioned directly above the printed name and title.

David H. Smith
Nuclear Licensing Administrator

cc: NRC Resident Inspector - Braidwood

9177N