

APPENDIX A

Texas Bolt Company
Docket No. 99900888/84-01

NOTICE OF VIOLATION

As a result of the inspection conducted on November 12-15, 1984, and in accordance with Section 206 of the Energy Reorganization Act of 1974 and its implementing regulation 10 CFR Part 21, the following violation was identified and categorized in accordance with the NRC Enforcement Policy (10 CFR Part 2, Appendix C), 49 FR 8583 (March 8, 1984):

Section 21.6 of 10 CFR Part 21 dated May 31, 1984, states, in part, "(a) Each ... corporation ... subject to the regulations in this part, shall post current copies of the following documents in a conspicuous position ... (1) the regulations in this part, (2) Section 206 of the Energy Reorganization Act, and (3) procedures adopted pursuant to the regulations in this part."

Contrary to the above, a copy of Section 206 of the Energy Reorganization Act was not posted in three areas of the manufacturing facility where 10 CFR Part 21 and Texas Bolt's (TB) Part 21 procedure were posted.

..

8501110050 850109
PDR GA999 EMVTEXB
99900888 PDR