

VIRGINIA ELECTRIC AND POWER COMPANY
RICHMOND, VIRGINIA 23261

June 9, 1997

United States Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D.C. 20555

Serial No. 97-343
NL&OS/ETS R0
Docket No. 50-338
License No. NPF-4

Gentlemen:

VIRGINIA ELECTRIC AND POWER COMPANY
NORTH ANNA POWER STATION UNIT 1
STEAM GENERATOR TUBE INSPECTION REPORT

Planned inservice inspection of the North Anna Unit 1 "A" steam generator was completed during the Spring 1997 refueling outage. In accordance with North Anna Power Station Technical Specifications, Surveillance Requirement 4.4.5.5.a, this letter provides notification that no steam generator tubes were plugged during the outage.

No new commitments are intended by this letter. If you have any questions concerning these results, please contact us.

Very truly yours,



S. P. Sarver, Acting Manager
Nuclear Licensing and Operations Support

cc: U. S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth St., SW, Suite 23T85
Atlanta, Georgia 30303

NRC Senior Resident Inspector
North Anna Power Station

9706170129 970609
PDR ADOCK 0500C338
PDR

160092



1/0
ADU1