Douglas R. Gipson Senior Vice President Nuclear Generation



6400 North Dixie Highway Newport, Michigan 48166 (313) 586-5249

10CFR50.73

May 12, 1997 NRC-97-0051

U. S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, D. C. 20555

Reference: 1) Fermi 2

Docket No. 50-341

NRC License No. NPF-43

2) Detroit Edison Letter to NRC, NRC-97-0029, "Licensee Event Report 97-005," dated April 7, 1997

Subject: Licensee Event Report (LER) No. 97-005, Revision 1

Pursuant to Fermi 2 License Condition 2.C.9 and 10CFR50.73(a)(2)(i)(B), Detroit Edison is submitting the enclosed LER No. 97-005, Revision 1, regarding inadequate design or consideration of circuits involved in achieving dedicated shutdown. The original LER (Reference 2) dealt with the Emergency Equipment Cooling Water (EECW) System makeup tank isolation valve interlocks potentially preventing operation of the EECW System from the Dedicated Shutdown Panel. However, due to additional discrepancies discovered in a review of the dedicated shutdown circuits performed as a corrective action from the original LER, the LER has been expanded to include these instances of affected dedicated shutdown circuits. All corrective actions related to this LER are complete.

There are no new commitments made in this LER.

9705190044 970512 ADOCK 05000341

160076

1/1 Te22

If you have any questions, please contact Norm Peterson, Compliance Supervisor, at (313) 586-4528.

Sincerely,

cc: A. B. Beach

G. A. Harris

M. J. Jordan

A. J. Kugler

M. V. Yudasz, Jr.

Region III

Wayne County Emergency Management Division