NRC Form 591 (12-81) 10 CFR 2.201		SAFETY I	SPECTION	U.S. NUCLEAR REGULATORY COMMISSION
				DMB COPY
LICENSEE CATERPILLAR TRACTOR CO. METALLURGICAL LAB. N. 27th ST. AT PERSHING RD. DECATUR, ILLINOIS 62525		2. REGIONAL OFFICE U.S. NUCLEAR REGULATORY COMMISSION REGION III 799 ROOSEVELT ROAD GLEN ELLYN, IL 60137		
DOCKET NU	MBER(S)	4. LICENSE NUMBER(S)		5. DATE OF INSPECTION
030-	030-14350 12-18023		3-01	FEB. 12, 1986
censee:				
egulatory Com nd representativ 1. Within the 2. The inspe those acti 3. During th	nmissions (NRC) rules and regula ve records, interviews, with personance with personance of this inspection, no vio	tions and the conditions of you onnel, and observations by the lations were observed. have taken to correct the violati	in license. The inspectionspector. The finding ons identified during the number of NRC rection of NRC rections.	
				was not properly posted to indicate the presen
of a				was not properly posted to indicate the present . 10 CFR 20.203(b), (c), (d), (e) or 34.4
_				
	einers located in d to indicate the presence of rad			were not proper
freque	encies. 10 CFR		License (_ of sealed sources were not performed at the prop Condition Number were not properly maintaine
10 CF	A		r License Condition N	
E. Docur	ments were not properly posted (or otherwise made available. 10	CFR 19.11.	
	rts or notifications of 10 CFR			were not made in accordance
			Chemise Condition 4	unter
H				
_ 1	and the state of			
J				
	8602250098	860212		
Ск	8602250098 REG3 LIC30 12-18023-01	PDR		
hereby state th his statement o	at within 30 days the actions de of corrective actions is made in a	scribed by me to the inspector scordance with the requirement	will be taken to correct ts of 10 CFR 2 201. No	t the violations identified in the items checked above o further response will be submitted unless required in the second s
he NRC.				and a second sec
	CICRATURE LIGENERS		Colleen	C. Carey 12/12/8
	SIGNATURE - LICENSEE	DATE	SIGNATU	RE NRCINSPECTOR
				TS