



Duke Power
A Duke Energy Company
McGuire Nuclear Generation Department
12700 Hagers Ferry Road (MG01VP)
Huntersville, NC 28078-9340

DATE: June 26, 1997

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, D.C. 20555

Subject: McGuire Nuclear Station, Unit 2
Docket No. 50-369
Licensee Event Report 370/97-01, Revision 0
Problem Investigation Process No.: PIP 2-M97-2175

Gentlemen:

Pursuant to 10 CFR 50.73 Sections (a) (1) and (d), attached is Licensee Event Report 370/97-01, Revision 0, concerning a Diesel Generator Load Sequencer Inadvertent Engineered Safety Feature Actuation. This report is being submitted in accordance with 10 CFR 50.73 (a) (2) (iv). This event is considered to be of no significance with respect to the health and safety of the public.

Very truly yours,

H. B. Barron, Jr.

JWP/bcb

Attachment

cc: Mr. L. A. Reyes
U.S. Nuclear Regulatory Commission
Region II
Atlanta Federal Center
61 Forsyth St., SW, Suite 23T85
Atlanta, GA 30323

INPO Records Center
700 Galleria Parkway
Atlanta, GA 30339

Mr. Victor Nerses
U.S. Nuclear Regulatory Commission
Office of Nuclear Reactor Regulation
Washington, D.C. 20555

Mr. Scott Shaeffer
NRC Resident Inspector
McGuire Nuclear Station

9707010312 970626
PDR ADOCK 05000370
S PDR

010055



IE221

bxc: B. L. Walsh (EC11C)
M. S. Kitlan (CNS)
G. A. Copp (EC050)
J. I. Glenn (MG02ME)
P. R. Herran (MG01VP)
L. S. Davis (MG05SE)
J. E. Burchfield (ONS Reg Compliance)
G. H. Savage (EC06E)
G. B. Swindlehurst (EC11-0842)
C. M. Misenheimer (EC08I)
R. F. Cole (EC05N)
J. M. Frye (EC05N)
T. G. Becker (PB02L)
P. M. Abraham (EC08I)
R. B. White (MG01VP)
R. T. Bond (ON03SR)
D. P. Kimball (CN05SR)
K. L. Crane (MG01RC)
R. N. Casler (EC05N)
NSRB Support Staff (EC05N)