



**Northeast
Nuclear Energy**

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System
May 15, 1997

Docket No. 50-336
B16453

Re: 10 CFR 50.73(a)(2)(i)(B)

U.S. Nuclear Regulatory Commission
Document Control Desk
Washington, DC 20555

This letter forwards Licensee Event Report (LER) 97-016-00, documenting an event that occurred at Millstone Nuclear Power Station, Unit No. 2 on April 15, 1997. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(i)(B).

The following are NNECO's commitments made within this letter.

B16453-01: The surveillance procedure for the Turbine Driven Auxiliary Feedwater (TDAFW) Pump will be revised prior to entry into Mode 4 from the current outage to ensure that the required 15 minute run of the TDAFW Pump is started from the CR and is performed prior to unit entry into Mode 3.

B16453-02: Technical Specification surveillance procedures will be reviewed to ensure compliance with Technical Specifications surveillance requirements as part of Millstone Unit 2 Operational Readiness Plan (Reference NOV 336/96-08-07, NNECO Commitment No. B16076-2).

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

M. L. Bowling

M. L. Bowling
Millstone Unit No. 2 Recovery Officer

9705220166 970515
PDR ADOCK 05000336
S PDR

cc: see page 2



11-11-97

U. S. Nuclear Regulatory Commission
B16453/Page 2

Attachment: LER 97-016-00

cc: W. D. Travers, Director of Special Projects
H. J. Miller, Region I Administrator
D. P. Beaulieu, Senior Resident Inspector, Millstone Unit No. 2
D. G. McDonald, Jr., NRC Senior Project Manager, Millstone Unit No. 2