



UNITED STATES
ATOMIC ENERGY COMMISSION
WASHINGTON, D.C. 20545

RECEIVED
January 28, 1972

1972 JAN 31 PM 12 44

Docket No. 50-219

U.S. ATOMIC ENERGY COMM.
ADVISORY COMMITTEE ON
REACTOR SAFEGUARDS

Dr. Chester P. Siess
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Dr. Siess:

Sixteen (16) copies of the following are transmitted for the
Committee's information:

Letter from Jersey Central Power & Light Company
dated January 25, 1972, advising that two control
rods (18-11 and 30-31) latched at position 02,
six inches short of fully inserted position 00,
when the reactor was manually tripped on 11/16/71,
at Oyster Creek.

Sincerely,

Donald J. Skovholt
Assistant Director
for Reactor Operations
Division of Reactor Licensing

Enclosures:
As stated

Category D
AGRS OFFICE COPY

1/26/85