



**Commonwealth Edison**

Dresden Nuclear Power Station  
R.R. #1  
Morris, Illinois 60450  
Telephone 815/942-2920

CEIL

D. Saxham

August 25, 1978

BBS LTR #78-1220

James G. Keppler, Regional Director  
Directorate of Regulatory Operations - Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Reportable Occurrence "Update Report" #78-030/01X-1, Docket #050-237 is hereby submitted to your office to report the corrective actions which have been taken to prevent recurrence of an error that resulted in the inoperability of the "A" LPCI and Core Spray Subsystems. This event was reported to your office under Dresden Nuclear Power Station Technical Specification 6.6.B.1.(f), personnel error which prevents or could prevent, by itself, the fulfillment of the functional requirements of systems required to cope with accidents analyzed in the S.A.R.

B. B. Stephenson  
Station Superintendent  
Dresden Nuclear Power Station

BBS/deb

Enclosure

cc: Director of Inspection and Enforcement  
Director of Management Information & Program Control  
File/NRC

SEP 11 1978

7809180320

A002  
5/11