January 24, 1997

Herbert Bell, M.D.
Chief Executive Officer
Mid America Cardiology
4321 Washington Avenue, Suite 4000
Kansas City, Missouri 64111

Dear Dr. Bell:

This refers to the inspection conducted on January 9, 1997 of your facilities located at 4321 Washington Avenue and 9411 North Oak Trafficway. The purpose of the inspection was to determine whether activities authorized by your license were conducted safely and in accordance with NRC requirements. At the conclusion of the inspection, the findings were discussed with you and members of your staff.

The inspection was an examination of activities conducted under your license as they relate to radiation safety and to compliance with the Commission's rules and regulations and with the conditions of your license. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, independent measurements and observation of activities in progress.

No violations of NRC requirements were noted. Further, no safety concerns were identified regarding the implementation of your radiation safety program. It is not necessary that you acknowledge receipt of this letter.

In accordance with 10 CFR 2.790 of the NRC's "Rules of Practice," a copy of this letter will be placed in the National Public Pocument Room (PDR).

Sincerely,

Original Signed by B. J. Holt

9701280344 970124 PDR ADOCK 03031959 C PDR Cynthia D. Pederson, Director Division of Nuclear Materials Safety

License No.: 24-26254-01 Docket No.: 030-31959

cc: PUBLIC

B. Clayton, EICS

280050

DOCUMENT NAME: G:\INSPRPTS\MTLS\030\03031959.971

To receive a copy of this document, indicate in the box: "C" = Copy without enclosures "E" = Copy with enclosures "N" = No copy

OFFICE	DNMS/RIII/	C	DNMS/RIII	N	DNMS/RIII	1 6			
NAME	Haysejawin		Phillips		Pederson 2944				
DATE	14797		16797		14/97	7. '			

110