

1 | G | A | F | I | H | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 1 | 1 | 1 | 1 | 4 | 5

1 | L | 0 | 5 | 0 | 0 | 0 | 3 | 6 | 6 | 7 | 1 | 1 | 0 | 9 | 7 | 8 | 8 | 1 | 1 | 2 | 2 | 7 | 8 | 9

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

The suppression chamber drywell vacuum breakers were not demonstrated operable within the two hour period required by Technical Specification 4.6.4.1, a. After discharge of steam to the suppression chambers from the safety/relief valves. There were no personnel injuries or overexposure or any release of radioactive materials to the environs as a result of this occurrence.

SYSTEM CODE: Z Z (11); CAUSE CODE: A (12); CAUSE SUBCODE: A (13); COMPONENT CODE: Z Z Z Z Z Z (14); COMP. SUBCODE: Z (15); VALVE SUBCODE: Z (16)

LER RO REPORT NUMBER: 7 8 (17); EVENT YEAR: 7 8 (21, 22); SEQUENTIAL REPORT NO.: 0 6 6 (24, 25, 26); OCCURRENCE CODE: 0 3 (28, 29); REPORT TYPE: L (30); REVISION NO.: 0 (32); ACTION TAKEN: H (33); FUTURE ACTION: 2 (34); EFFECT ON PLANT: 2 (35); SHUTDOWN METHOD: Z (36); HOURS: 0 0 0 (37, 38, 39); ATTACHMENT SUBMITTED: N (41); NRPD-4 FORM SUB.: N (42); PRIME COMP. SUPPLIER: Z (43); COMPONENT MANUFACTURER: 2 9 9 9 (44, 45, 46, 47)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

The Technical Specification requirement to test suppression chamber - drywell vacuum breakers was overlooked by operating personnel. The vacuum breaker test was performed as soon as missed surveillance was discovered. Operating personnel have been instructed to pay closer attention to Technical Specification Requirements.

FACILITY STATUS: B (23); % POWER: 0 0 1 (24, 25, 26); OTHER STATUS: NA (30); METHOD OF DISCOVERY: A (31); DISCOVERY DESCRIPTION: Operator observation (32); ACTIVITY CONTENT RELEASED OF RELEASE: Z (33); AMOUNT OF ACTIVITY: NA (35); LOCATION OF RELEASE: NA (36)

PERSONNEL EXPOSURES NUMBER: 0 0 0 (37); TYPE: Z (38); DESCRIPTION: NA (39)

PERSONNEL INJURIES NUMBER: 0 0 0 (40); DESCRIPTION: NA (41)

LOSS OF OR DAMAGE TO FACILITY TYPE: Z (42); DESCRIPTION: NA (43)

PUBLICITY ISSUED DESCRIPTION: N (44); DESCRIPTION: NA (45)

7812180186

NAME OF PREPARER: S. y. Baxley Supt. of Operations PHONE: 912-367-7781

GPO 91-7-328