In Reply Refer To: Docket: 50-458/88-02

Gulf States Utilities

ATTN: Mr. James C. Deddens Senior Vice President, (RBNG)

Nuclear Licensing

P.O. Box 220

St. Francisville, Louisiana 70775

Gentlemen:

This refers to the inspection conducted by Messrs. D. E. Norman and R. V. Azua of this office during the period January 19-22, 1988, of activities authorized by NRC Operating License NPF-47 for River Bend Station, and to the discussion of our findings with you and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection included a followup of actions related to IE Bulletin 85-03. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspectors. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

Three unresolved items are identified in paragraphs 2.c(3) and 2.d(4) of the enclosed inspection report.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

Original Signed by M. B. Beach

L. J. Callan, Director Division of Reactor Projects

Enclosure: (see next page)

RIV: DRS/RI* DENorman; dp / /88

AC: PSS* REIreland / /88

RI* RVAzua / /88

C: TPS* WSeidle / /88

C: DRP/C* D: DRS* JLMilhoan EHoller / /88 / /88

D: DRPL 5 JLCal Yan 2 /26/88

Reconcura REIreland 2/29/88

8803030265 880229 ADDCK 05000458

In Reply Refer To: Docket: 50-458/88-02

Gulf States Utilities

ATTN: Mr. James C. Deddens

Senior Vice President, (RBNG)

Nuclear Licensing

P.O. Box 220

St. Francisville, Louisiana 70775

Gentlemen:

This refers to the inspection conducted by Messrs. D. E. Norman and R. V. Azua of this office during the period January 19-22, 1988, of activities authorized by NRC Operating License NPF-47 for River Bend Station, and to the discussion of our findings with you and other members of your staff at the conclusion of the inspection.

Areas examined during the inspection included a followup of actions related to IE Bulletin 85-03. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the NRC inspectors. The inspection findings are documented in the enclosed inspection report.

Within the scope of the inspection, no violations or deviations were identified.

RVAzua

Three unresolved items are identified in paragraphs 2.c(3) and 2.c(4) of the enclosed inspection report.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

L. J. Callan, Director Division of Reacto: Projects

Enclosure: (see next page)

RIV: DRS/RI Han DENorman; dp 19 REIreland 2 /23 /88

D: DRP

JLCallan

/ /88

Reconcur RIreland

/ /88

WSeidle 2/23/88

2/23/88

lhoan EHoller

Enclosure: Appendix - NRC Inspection Report 50-458/88-02

cc w/enclosure: Gulf States Utilities ATTN: J. E. Booker, Manager-River Bend Oversight P.O. Box 2951 Beaumont, Texas 77704

Louisiana State University, Government Documents Department

Louisiana Radiation Control Program Director

bcc to DMB (IEO1)

bcc distrib. by RIV: *DRP R. D. Martin, RA Lisa Shea, RM/ALF RPSB-DRSS *Project Engineer, DRP/C

*W. Paulson, NRR Project Manager *R. Hall Carl H. Berlinger, NRR/DOEA

*TSS

D. Powers *D. Norman *R. Azua

*w/766

*Resident Inspector

*Section Chief (DRP/C)

*MIS System *RSTS Operator

*RIV File

*DRS