

DMB COPY

FEB 29 1988

The Ohmart Corporation
ATTN: Mr. Paul E. Sieck
Vice President, Manufacturing
4241 Allendorf Drive
Cincinnati, OH 45209

License No. 34-00639-01

Gentlemen:

This refers to the special safety inspection conducted by S. R. Lasuk of this office on February 4-5, 1988, of activities authorized by NRC Byproduct Materials License No. 34-00639-01 and to the discussion of our findings with you at the conclusion of the inspection. This also refers to the telephone discussion between you and Mr. Lasuk on February 10, 1988, regarding a memorandum you will issue to your field representatives in the near future.

The inspection was conducted as a result of a concern expressed by our Region I office regarding certain technical advice provided to a licensee by Ohmart representatives. The above memorandum, which contains guidelines for discussions on radiation exposures, adequately addresses that concern.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8803070291 880229
REG3 LIC30
34-00639-01 PDR

Bruce S. Mallett, Ph.D., Chief
Nuclear Materials Safety and
Safeguards Branch

Enclosure: Inspection Report
No. 030-05634/88001(DRSS)

cc w/enclosure:
DCD/DCB (RIDS)

RIII **YES**
SRZ
Lasuk/jlr
2/24/88

YES
RIII *Jw*
Wiedeman

YES
RIII
BSm
Mallett
2/25/88

IE07
/