IE07

NRC FORM 591 PART 1

(7-91)

10 CFR 2.201

SAFETY INSPECTION

U.S. NUCLEAR REGULATORY COMMISSION

			Page 1 of/_
1. LICENSEE Madiral X/ 14175, Min Sioux Falls	nes Aac	2. REGIONAL OFFICE REGIO U S NI 611 RV ARLINI	UCLEAR REGULATORY COMMISSION VAN PLAZA DRIVE SUITE 400 GTON TX 76011-8064
Sioux Falls, 3. DOCKET NUMBER(S) 97-01 Report No. 97-01 030-33335	4. LICENSE NUMBER(S) 40 - 274	80-01	5. DATE OF INSPECTION 2/12/97
LICENSEE: The inspection was an examination of the acti Regulatory Commission (NRC) rules and regu	lations and the conditions	of your license. The in	to radiation safety and to compliance with the Nuclear spection consisted of selective examinations of ector. The findings as a result of this inspection are as
3. During this inspection certain of you NOTICE OF VIOLATION, which is reconstructed.	you have taken to correct ne. r activities, as described b	the violations identified	
indicate the presence of a			was not properly posted to 10 CFR 20.203(b),(c),(d),(e) or 34.42.
В			of sealed sources were not
performed at the proper frequency C. Records of			e Condition Number were not properly maintained.
D. Documents were not properly E. Reports or notification of 10 CFR F.	posted or otherwise made	e available. 10 CFR 19.	were not made in accordance with
9703280261 970212 PDR ADOCK 03033333 C PDR	5		
I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified in the items checked above. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201. No further response will be submitted unless required by the NRC.			
SIGNATURE LICENSEE	DATE 2//3/32	SIGNATURE NRC IN	SPECTOR DATE, 2/10/97