

Tennessee Valley Authority, Post Office Box 2000, Soddy-Daisy, Tennessee 37379-2000

R.J. Adney
Site Vice President
Sequoyah Nuclear Plant

May 1, 1997


U.S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, D.C. 20555

Gentlemen:

TENNESSEE VALLEY AUTHORITY - SEQUOYAH NUCLEAR PLANT (SQN)
UNITS 1 AND 2 - DOCKET NOS. 50-327 AND 50-328 - FACILITY OPERATING
LICENSES DPR-77 AND DPR-79 - LICENSEE EVENT REPORT (LER) 50-327/97007

The enclosed report provides details concerning the start of the three available diesel generators that occurred as the result of a cable that was cut while drilling a hole in a control room electrical panel. The report also provides details of an event that occurred during the repair activities of the damaged cable that also resulted in the start of the three available diesel generators. This report is being reported in accordance with 10 CFR 50.73(a)(2)(iv) as a condition that resulted in the actuation of engineered safety features.

Sincerely,



R. J. Adney

Enclosure
cc: See page 2

IE22/1

9705070143 970501
PDR ADOCK 05000327
S PDR



U.S. Nuclear Regulatory Commission

Page 2

May 1, 1997

Enclosure

cc (Enclosure):

INPO Records Center
Institute of Nuclear Power Operations
700 Galleria Parkway
Atlanta, Georgia 30339-5957

Mr. R. W. Hernan, Project Manager
U.S. Nuclear Regulatory Commission
One White Flint, North
11555 Rockville Pike
Rockville, Maryland 20852-2739

NRC Resident Inspector
Sequoyah Nuclear Plant
2600 Igou Ferry Road
Soddy-Daisy, Tennessee 37379-3624

Regional Administrator
U.S. Nuclear Regulatory Commission
Region II
61 Forsythe St., SW, Suite 23T85
Atlanta, Georgia 30323-2711