

W. E. Ehrensperger  
Senior Vice President  
Power Supply

December 20, 1978

United States Nuclear Regulatory Commission  
Office of Inspection and Enforcement  
Region II - Suite 1217  
230 Peachtree Street, N.W.  
Atlanta, Georgia 30303

REFERENCE:  
50-424  
Vogtle 1  
50-425  
Vogtle 2

ATTENTION: Mr. James P. O'Reilly

Gentlemen:

A problem with embed assemblies was recently detected at the Vogtle Nuclear Plant - Units 1 & 2. Based on our review of the problem, it could constitute a possible significant deficiency per 10CFR50.55(e).

In accordance with NRC regulation, we are submitting an interim report. A final report will be submitted upon completion of the technical evaluation.

Very truly yours,

*W. E. Ehrensperger*  
W. E. Ehrensperger

CWH:db

Attachment

xc: U.S. Nuclear Regulatory Commission  
Attn: John G. Davis, Acting Director  
Office of Inspection and Enforcement  
Washington, D.C. 20555 (w/Attachment)

M. D. Hunt, NRC Region II (w/Attachment)

7812290145

Bo19  
5/11