Docket No. 50-346

Toledo Edison Company ATTN: Mr. Donald Shelton Vice President

Nuclear

Edison Plaza 300 Madison Avenue Toleda, OH 43652

Gentlemen:

This refers to the special safety inspection conducted by Mr. P. R. Wohld of this office on June 24-26, 1987, of activities at the Davis-Besse Nuclear Power Station, the review of information received from your staff during the period December 11-17, 1987, and to the discussion of our findings with Mr. S. J. Smith and others of your staff at the conclusion of the inspection. This inspection was conducted to evaluate the licensee's program developed to address IEB 85-03.

The enclosed copy of our inspection report identifies areas examined during the inspection. Within these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

8801260065 880115 PDR ADOCK 05000346 Q PDR ORIGINAL SIGNED BY GEOFFREY C. WRIGHT

G. C. Wright, Chief Operations Branch

Enclosure: Inspection Report No. 50-346/87017(DRS)

See Attached Distribution

Wohld/abl

RIII Huber

Phillips

DeFayette

RIII Wright &

IN JEO

Distribution

cc w/enclosure:
L. Storz, Plant Manager
DCD/DCB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII
Harold W. Kohn, Ohio EPA
James W. Harris, State of Ohio
Robert M. Quillin, Ohio
Department of Health
State of Ohio, Public
Utilities Commission
C. H. Berlinger, OGCB/NRR