



Log # TXX-88042
File # 10110
910.4
Ref. # 10CFR50.55(e)

William G. Council
Executive Vice President

January 19, 1988

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)
DOCKET NOS. 50-445 AND 50-446
TURBINE DRIVEN AUXILIARY FEEDWATER PUMP
BEARING TEMPERATURE
SDAR: CP-87-50 (SUPPLEMENTAL REPORT)

Gentlemen:

On July 27, 1987, we verbally notified your Mr. H. S. Phillips of a deficiency involving abnormal thrust bearing temperatures on the Turbine Driven Auxiliary Feedwater Pump. Our last report, logged TXX-6954 dated November 13, 1987, provided a schedule for the completion of corrective actions to resolve this deficiency. Due to delays in supply of material and repair instructions by the vendor, the schedule provided in TXX-6954 will not be met. The new schedule for completion, based upon projected availability of spare parts and finalized repair instructions from the vendor, is February 15, 1988, for all Unit 1 AFW Pumps. We will initiate corrective action on Unit 2 after completion of the Unit 1 work, and will advise you accordingly.

Very truly yours,

W. G. Council

W. G. Council

By: *D. R. Woodlan*

D. R. Woodlan
Supervisor,
Docket Licensing

JDS/grr

c - Mr. R. D. Martin, Region IV
Resident Inspectors, CPSES (3)

8801760137 880119
PDR ADDCK 05000445
S PDR

*IF27
1/9*