

Appendix A

NOTICE OF VIOLATIONS

Concordia College

License No. SNM-773

Based on the inspection conducted on September 14, 1978, it appears that certain of your activities were in noncompliance with NRC requirements, as noted below. Item 1 is an infraction, and items 2 and 3 are deficiencies.

1. License Condition No. 13.A. of NRC Special Nuclear Material License No. SNM-773, states in part that each encapsulated plutonium source shall be tested for leakage at intervals not to exceed six (6) months.

Contrary to the requirement as of the date of this inspection leak tests had been performed May 2, 1975, January 29, 1976, and March 19, 1977, intervals in excess of the specified frequency.

2. Paragraphs 10 CFR 19.11(a) and (b), Title 10 of the Code of Federal Regulations, Part 19, requires that current copies of Part 19, Part 20, license conditions, documents incorporated into the license, license amendments and operating procedures be posted, or a notice describing these documents and where they may be examined, be posted.

Contrary to these requirements, on the date of this inspection, neither the documents nor the notice of their availability were posted.

3. Paragraph 10 CFR 19.11(c) in Title 10 of the Code of Federal Regulations, Part 19, requires that form NRC-3, "Notice to Employees," be posted wherever individuals work in or frequent a restricted area.

Contrary to this requirement, on the date of this inspection, form NRC-3 was not posted.

781107 0295