

Public Service  
Company of Colorado

2420 W. 26th Avenue, Suite 100D, Denver, Colorado 80211

March 21, 1988  
Fort St. Vrain  
Unit No. 1  
P-88096

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, D.C. 20555

Docket No. 50-267

SUBJECT: Updated FSAR, Revision 5

Gentlemen:

As discussed by telephone March 9, 1988 between Mr. Bill McNeil, NRC, Region IV, and Mr. Phil Tomlinson, Manager, QA Division, the following Updated Final Safety Analysis Report (UFSAR) Appendix B, Revision 5 sections were identified as requiring clarification:

1. Section B.5.1.4., Nuclear Production Division, Quality Assurance Related Responsibilities - need additional information to address all functions in section B.5.1.4 of Rev. 4, such as review of controlled work procedures, security, etc.
2. Section B.5.2.1, Program Description (2nd paragraph) - indicate that these items are controlled by the QA Program and referenced as such throughout Appendix B, and that QA Program controls are not limited to just these items.
3. Section B.5.15.1, Documenting, Nonconforming Items - clarify the use of Station Service Requests (SSR's) in addition to Nonconformance Reports, and describe SSR trending.


8803280271 880321  
PDR ADOCK 05000267  
P DCD

A053  
1/0

March 21, 1988

It was agreed that the above corrections or clarifications would be addressed and included in UFSAR Appendix B, Revision 6. If you have any questions or comments, please contact Mr. M. H. Holmes at (303) 480-6960.

Very Truly Yours,



H. L. Brey, Manager  
Nuclear Licensing  
and Fuels

HLB/PFM:lme

cc: Regional Administrator, Region IV  
ATTN: Mr. T. F. Westerman, Chief  
Projects Section B

U.S. Nuclear Regulatory Commission  
511 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Mr. Bill McNeil  
U.S. Nuclear Regulatory Commission  
611 Ryan Plaza Drive, Suite 1000  
Arlington, Texas 76011

Mr. Robert Farrell  
Senior Resident Inspector  
Fort St. Vrain