

*Central Files*

OCT 31 1980

NOV 10 PM 2 19

ENGINEERING SERVICES  
BRANCH

RECEIVED

Socket No. 50-546  
Socket No. 50-547

Public Service of Indiana  
ATTN: Mr. S. W. Shields  
Senior Vice President  
Nuclear Division  
Post Office Box 190  
New Washington, IN 47162

Gentlemen:

Thank you for your interim report dated October 24, 1980, pursuant to 10 CFR 50.55(e) regarding deficiencies found in a number of welds on cable tray hangers during maintenance of storage conditions. We will review your final report on this matter upon receipt.

Your cooperation with us is appreciated.

Sincerely,

Gaston Fiorelli, Chief  
Reactor Construction and  
Engineering Support Branch

cc: Director, RCI/II  
Director, AEOD  
Chief, OEB/MPA  
IE Files  
Mr. G. N. Brown, Project  
Director  
C. Kammerer, CA


cc w/ltr dtd 10/24/80:  
Central Files  
PDR  
Local PDR  
NSIC  
TIC  
LaBoeuf, Lamb, Leiby & MacRae  
Mr. Dave Martin, Office of  
Attorney General  
Mr. John R. Galloway, Staff  
Director, Environment, Energy  
and Natural Resources Subcommittee

THIS DOCUMENT CONTAINS  
POOR QUALITY PAGES

8011190503

5

OFFICE	RIII <i>SPB</i>	RIII <i>AW</i>	RIII <i>Y</i>			
SURNAME	Schweibinz/ <i>sw</i>	Williams	Fiorelli			
DATE	10/30/80	10/29/80				



1023804013

**PUBLIC  
SERVICE  
INDIANA**

S. W. Shields  
Senior Vice President -  
Nuclear Division

October 24, 1980

Mr. James G. Keppler, Director  
U. S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Docket Nos.: STN 50-546  
STN 50-547  
Construction Permit Nos.:  
CPPR - 170  
CPPR - 171

Marble Hill Nuclear Generating Station - Units 1 and 2


Dear Mr. Keppler:

On September 25, 1980, Mr. S. J. Brewer of Public Service Company of Indiana, Inc., (PSI) notified your office of a potentially reportable item as required by 10 CFR 50.55(e). During maintenance of storage conditions on cable tray hangers, deficiencies were identified in a number of their welds. A nonconformance report was issued by the contractor who identified the deficiencies and was submitted to PSI for evaluation and disposition.

PSI has performed an evaluation of those deficiencies which included a reinspection of the cable tray hangers in question. Most of the welds in question proved to be acceptable and only a small number will require rework. However, since the preliminary telephone notification, additional weld deficiencies have been identified and these will require additional time for evaluation.

This letter is intended to fulfill the requirements of an interim report as defined by 10 CFR 50.55(e). A final report will be submitted on or before December 5, 1980. If you have any questions please feel free to contact me.

Sincerely,

  
S. W. Shields

TDG/cg

*dupe of 8010290367*

PUBLIC  
SERVICE  
INDIANA

Letter: James G. Keppler

-2-

October 24, 1980

cc: Director of Inspection and Information  
U. S. Nuclear Regulatory Commission  
Washington, D. C. 20555

E. R. Schweibinz, P. E.  
J. J. Harrison