William J. Cahill, Jr.
Vice President

Consolidated Edison Co.
4 Irving Place, New Yo

Consolidated Edison Company of New York, Inc. 4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

November 9, 1978

Re: Indian Point Units 1 and 2 Docket Mos. 50-3 50-247

Director of Nuclear Reactor Regulation:

ATTN: Mr. Albert Schwencer, Chief
Operating Reactors Branch #1
Division of Operating Reactor
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Mr. Schwencer:

We have been informed by the Regulatory Staff that several items in the Indian Point Units 1 and 2 Modified Amended Security Plan (MASP) remain unresolved.

In response to certain of these items, forwarded herewith are five(5) copies of Enclosure 1 to this letter containing revisions to the Indian Point Units 1&2 MASP. In addition, this Enclosure also contains a revision relating to the isolation zone width along the Unit I Screenwell House as previously discussed with the Staff. Finally, alternative positions to the remaining items are set forth in Enclosure 2 to this letter. We believe these enclosures satisfactorily address all remaining unresolved items in the MASP for Indian Point Units 1 & 2.

In accordance with Section 2.790(d) of the Commission's Rules of Practice, we request that this letter and its enclosures be withheld from public disclosure.

Very truly yours,

William J. Cahill, Jr.

Vice-President

Enclosure

505/5