

J. H. MAXYMILLIAN, INC.

General Contracting

OFFICE: 1801 EAST STREET • PITTSFIELD, MA 01201 • PHONE: (413) 499-3050

January 12, 1988

United States
Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

Attn: John D. Kinneman, Chief
Nuclear Materials Safety Section A
Division of Radiation Safety and Safeguards

Re: License No. 20-20853-01
Docket No. 030-21266
Routine Inspection No. 87-001 -9/14/87

Gentlemen:

In response to your letter and notice of violation (copy enclosed) we offer the following:

1. We have informed personnel authorized to use and/or perform leak tests on the gauge that a bill of lading, source certificate and training certificate be kept with the gauge during transport. The gauge has not been transported since that time.
2. We have issued a memo (copy enclosed) to be kept in the room with the gauge along with the posters and signs required. This memo states proper transport procedure. In the future, all required paperwork will be transported with the gauge.
3. Full compliance has been achieved as of this date.

If you have any questions or require further information, please do not hesitate to call me.

Very truly yours,
J. H. MAXYMILLIAN, INC.



Anthony J. Simonelli
Radiation Safety Officer

8804070287 880328
REG1 LIC30
20-20853-01 PDR

AJS/bep
Enclosures

cc: James H. Maxymillian

J. H. MAXYMILLIAN, INC.

General Contracting

OFFICE: 1801 EAST STREET • PITTSFIELD, MA 01201 • PHONE: (413) 499-3050

January 12, 1988

United States
Nuclear Regulatory Commission
Region I
631 Park Avenue
King of Prussia, PA 19406

Attn: John D. Kinneman, Chief
Nuclear Materials Safety Section A
Division of Radiation Safety and Safeguards

Re: License No. 20-20853-01
Docket No. 030-21266
Routine Inspection No. 87-001 -9/14/87

Gentlemen:

In response to your letter and notice of violation (copy enclosed) we offer the following:

1. We have informed personnel authorized to use and/or perform leak tests on the gauge that a bill of lading, source certificate and training certificate be kept with the gauge during transport. The gauge has not been transported since that time.
2. We have issued a memo (copy enclosed) to be kept in the room with the gauge along with the posters and signs required. This memo states proper transport procedure. In the future, all required paperwork will be transported with the gauge.
3. Full compliance has been achieved as of this date.

If you have any questions or require further information, please do not hesitate to call me.

Very truly yours,
J. H. MAXYMILLIAN, INC.



Anthony J. Simonelli
Radiation Safety Officer

8804070287 880328
REG1 LIC30
20-20853-01 PDR

AJS/bep
Enclosures

cc: James H. Maxymillian

RECEIVED-REGION I
JAN 14 1988

January 12, 1988

TO: ALL PERSONNEL AUTHORIZED TO HANDLE TROXLER GAUGE
FROM: TONY SIMONELLI, RADIATION SAFETY OFFICER
SUBJECT: PROPER PROCEDURE FOR TRANSPORT OF GAUGE

The Troxler gauge is not to be removed from this site without the following paperwork:

1. Bill of Lading
2. Source Certificate
3. Training Certificate

Please see Robyn Parslow before transporting this gauge and she will obtain the proper paperwork.

Also, please fill out the log book every time the gauge is used or tested.



Tony Simonelli
Radiation Safety Officer