

*pd*

November 2, 1978

A. B. Davis  
Chief Fuel Facility and Materials Safety Branch  
U.S. Nuclear Regulatory Commission  
Region 3  
799 Roosevelt Road  
Glen Ellyn, IL 60137

48-17514-01

Dear Mr. Davis,

In regard to the inspection conducted by Mr. Hyatt at Mid-State Technical Institute, Wisconsin Rapids, Wisconsin earlier this year, we (Mid-State) have taken the following action to correct what Mr. Hyatt felt were unsafe practices.

1. We have obtained an additional film badge from Landauer and this film badge will be worn whenever any person operates the density meter. This means that we now have two film badges at Mid-State for the purpose of checking the density meter.

The two film badges will be sent to Landauer on a monthly basis and we have entered into a yearly contract with Landauer.

I believe this should correct the problem that Mr. Hyatt noticed. If additional steps need be taken, please let me know.

Sincerely,

*David C. Kersten*

David C. Kersten  
Mid-State Technical Institute

7811290084

NOV 6 1978