

Detroit
Edison

B. Ralph Sylvia
Group Vice President

5400 North Dixie Highway
Newport, Michigan 48166
(313) 586-4150

April 6, 1988
NRC-88-0100

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, D. C. 20555

Reference: Fermi 2
NRC Docket No. 50-341
NRC License No. NPF-43


Subject: Errata to UFSAR Revision 1

Please include the attached errata with Revision 1 to the Fermi 2 UFSAR previously submitted by our letter, file number NRC-88-0066, dated March 17, 1988. This errata includes the following pages, which are to replace like-numbered pages in the revision package:
Revision 1 Instructions pages 9 and 10, List of Effective Pages, pages LEP-57 and LEP-58, and UFSAR page 13.2-11/Blank.

This errata corrects an error made in the process of assembling Revision 1 of the UFSAR for printing.

If you have any questions, please contact Ms. Lynne Goodman at (313) 586-4211.

Sincerely,



cc: A. B. Davis
R. C Knop
T. R. Quay
W. G. Rogers
USNRC Region III

8804140025 880406
PDR ADOCK 05000341
K DCD

A053
11