Ailas Minerals

Division of Allas Corporation

8000 East Evans Avenue, Suite 401,

Denver, Colorado 80222

5 Phone (803) 757-1750

Gordon T. Swacoy



December 12, 1980



Mr. Ross Scarano, Branch Chief Uranium Recovery Licensing Branch Division of Waste Management Nuclear Regulatory Commission Washington, D.C. 20555

Dear Mr. Scarano:

Enclosed please find a copy of a report on the Atlas attempt to produce water from the mill tailings pile. This is the report that I promised to send to Terry Van Dell.

Very truly yours,

ordon T. Swanly

La Line is

Gordon T. Swanby

GTS:rf

Enc: Report

cc: R. R. Weaver

Robert Alcock

MAIN OFFICE
P. O. DRAWER 30
ALICE, TEXAS 78332
TELEPHONE (512) 664 9935

REPLY 10
EUGEMONT BRANCH P. O. BOX 10727
GOLDEN, COLORADO 80401
TELEPHONE (10.3), 232 6649

SOLUTION ENGINEERING, INC.

June 18, 1979

Mr. Waynard M. Jensen Atlas Minerals P. O. Box 1207

Dear Wayne:

Moab, Utah 84532

Solution Engineering, Inc. respectfully submits the enclosed report of preliminary hydrological testing performed in the Atlas mill tailings.

Although the results of field testing were less than favorable, there is a reasonable probability that continued work may develop the feasibility of extracting uranium from the tailings by "in situ" techniques. Appropriate recommendations are provided in the report.

I will contact you in a week or so to discuss the program further.

Yours very truly,

S. R. Stanolow

Joseph R. Stano Vice President

/ jo

Inc. Report