

Appendix A  
Notice of Violation

BMY  
Division of Harsco Corporation  
York, Pennsylvania 17405

29026  
Docket No. 030-20718  
License No. 37-20684-02

As a result of the inspection conducted on June 4, 1987, and in accordance with the NRC Enforcement Policy (10 CFR 2, Appendix C), the following violation was identified:

10 CFR 20.201(b) requires that each licensee make such surveys as may be necessary to comply with all sections of Part 20. As defined in 10 CFR 20.201(a), "survey" means an evaluation of the radiation hazards incident to the production, use, release, disposal, or presence of radioactive materials or other sources of radiation under a specific set of conditions.

Contrary to the above, a required survey (evaluations) was not made to assure compliance with 10 CFR 20.101. Specifically, the personnel monitoring devices issued to radiographers in the month of February 1987 were not processed and no evaluation was made to determine the doses for the month.

This is a Severity Level IV violation. (Supplement IV)

Pursuant to the provisions of 10 CFR 2.201, BMY, Division of Harsco Corporation is hereby required to submit to this office within thirty days of the date of the letter which transmitted this Notice, a written statement or explanation in reply, including; (1) the corrective steps which have been taken and the results achieved; (2) corrective steps which will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Where good cause is shown, consideration will be given to extending this response time.

8802020075 870827  
REG1 LIC30 PDR  
37-20684-02

OFFICIAL RECORD COPY