APR 1 1 1988

Docket No. 50-454 Docket No. 50-455

Commonwealth Edison Company ATTN: Mr. Cordell Reed Senior Vice President Post Office Box 767 Chicago, IA 60690

Gentlemen:

This refers to the routine safety inspection conducted by Mr. P. G. Brochman and Ms. K. V. Gilles of this office from February 12 through March 31, 1988, of activities at Byron Station Units 1 and 2, authorized by NRC Operating Licenses No. NPF-37 and No. NPF-66, and to the discussion of our findings with Mr. R. Pleniewicz and others of your staff at the conclusion of the inspection.

The enclosed copy of our inspection report identifies areas examined during the inspection. Mithin these areas, the inspection consisted of a selective examination of procedures and representative records, observations, and interviews with personnel.

No violations of NRC requirements were identified during the course of this inspection.

In accordance with 10 CFR 2.790 of the Commission's regulations, a copy of this letter and the enclosed inspection report will be placed in the NRC Public Document Room.

We will gladly discuss any questions you have concerning this inspection.

Sincerely,

"Original Signed by J. M. Hinds, Jr."

William L. Forney, Chief, Reactor Projects Branch 1

Enclosure: Inspection Reports No. 50-454/88006(DRP); No. 50-455/88006(DRP) See Attached Distribution

ZE OI

Distribution

cc w/enclosure:
T. Maiman, Vice President,
PWR Operations
H. Bliss, Nuclear Licensing
Manager
R. Pleniewicz, Station Manager
DCS/RSB (RIDS)
Licensing Fee Management Branch
Resident Inspector, RIII Byron
Resident Inspector, RIII Braidwood
L. Olshan, NRR PM
J. McCaffrey, Chief, Public
Utilities Division
D. Cassel, Jr., Esq.
Diane Chavez, DAARE/SAFE
Richard Hubbard
H. Taylor, QA Division

RIII

Yew
For Brochman/jp

A/7/88

RIII VanSickle RIII Hinds 4.11.88



RIII